## B.E. Electronics Engineering Fourth Semester EN 405 - Basic Electrical Machines

| P. Pages : 3<br>Time : Three Hour |   |  | S * 1 2 2 7 *  |   |  |  |   |                               |                                | G                              | GUG/W/18/1558<br>Max. Marks : 80 |                   |                     |        |   |
|-----------------------------------|---|--|--|---|--|--|---|-------------------------------|--------------------------------|--------------------------------|----------------------------------|-------------------|---------------------|--------|---|
|                                   | Note  | s: 1.<br>2.<br>3.<br>4.<br>5.<br>6.  | All quest<br>Answer f<br>Due cred<br>Assume s<br>Illustrate<br>Use of sli<br>permitted | ions carry ed<br><b>ive</b> question<br>it will be given<br>suitable data<br>your answe<br>de rule, Dra | qual m<br>as as pe<br>ven to<br>where<br>rs whe<br>awing b | arks.<br>er the<br>neathe<br>ever n<br>rever<br>Instru | instrucess.<br>ecessa<br>necess<br>ments, | ry.<br>sary w                 | given<br>vith the              | e help<br>mmab                 | of nea<br>le calc                | t sket            | ches.<br>r is       |        |   |
| 1.                                | a) Draw and explain in brief the phasor diagram of single phase transformer considering winding resistance and leakage reactance for lagging and leading power factor load. |  |  |   |  |  | 5   | 8                             |                                |                                |                                  |                   |                     |        |   |
|                                   | b)  | <ul> <li>A 5 KVA, 200/1000 V, 50 Hz, single phase transformer gave the following test results:</li> <li>O. C. Test (L.V.Side) :- 200 V, 1.2 A, 90 W.</li> <li>S.C. Test (H.V. side) :- 50 V, 5A, 1.10 W.</li> <li>i) Compute the parameter of the approximate equivalent circuit referred to its L.V. side.</li> <li>ii) Draw the equivalent circuit referred to the L.V. side.</li> </ul> |  |   |  |  |   |                               |                                | 8                              |                                  |                   |                     |        |   |
|                                   |   |  |  |   |  |  | OR  |                               |                                |                                |                                  |                   |                     |        |   |
| 2.                                | a)  | State the conditions for the parallel operation of 3-phase transformer. Discuss the necessity of the parallel operation.   |  |   |  |  |   |                               |                                | 4                              |                                  |                   |                     |        |   |
|                                   | b)  | A 140 I<br>1750 W<br>transfor<br>i) Fu<br>ii) Ha<br>iii) Th  | XVA, 6000<br>7. The max<br>mer at-<br>11 load and<br>alf load and<br>he maximum        | /400 V, star<br>imum effici<br>0.8 p.f. lug<br>l upf.<br>m efficiency                                   | ency o<br>ging.  | onnec  | eted 3-<br>at the                         | phase $\frac{3}{4}$ th        | transf<br>full lo              | ormer<br>ad. Fi                | has and the                      | n iron<br>efficio | loss of<br>encies o | of the | 8 |
|                                   | c)  | Derive the emf equation of transformer.  |  |   |  |  |   |                               |                                |                                |                                  | 4                 |                     |        |   |
| 3.                                | a)  | Classify d. c. generator according to the manner in which field winding is exited. Draw <b>8</b> circuit diagram and write their voltage equations.  |  |   |  |  |   |                               |                                |                                |                                  |                   |                     |        |   |
|                                   | b)  | The fol<br>Fo<br>i) Vo   | lowing data<br>r this gene<br>oltage on o  | a is obtained<br>$I_{f} (Amp)$ $E_{g} (Volt)$ rator obtain<br>pen circuit t                             | 1 for m<br>2<br>110<br>:<br>o whic                         | agnet<br>3<br>155<br>ch mac                            | isation<br>4<br>186<br>chine v            | n curv<br>5<br>212<br>will bu | e of d.<br>6<br>230<br>uild ur | c. shu<br>7<br>246<br>9 for sl | nt ger<br>8<br>260<br>nunt re    | erato             | r at 400            | ) rpm. | 8 |

- ii) Resistance of shunt circuit to reduce the open circuit voltage to 220 V.iii) The speed at which the machine just fails to excite.
- iv) Residual flux per pole.

- ii) Capacitor start induction motor. OR
- Why starter is necessary in 3-phase inductor motor. Which are the various starters in 8. a) induction motor? Explain one method each for squirrel cage and slip ring induction motor.

2

b) Draw and explain the exact equivalent circuit of 3-phase induction motor.

4.

5.

a)

b)

c)

a)

b)

c)

a)

b)

a)

b)

6.

7.

| Deri   | ive the condition for maximum effi  | ciency                        | of d.c. shunt generator.   |  |  |  |  |  |  |
|--|---|-------------------------------|--|--|--|--|--|--|--|
| Wha  | at do you mean by mechanical, elec  | ctrical a                     | and commercial efficiency of d. c. generator.  |  |  |  |  |  |  |
| A sh<br>field  | nunt generator delivers 195 Amp at<br>l resistances are $0.02\Omega$ and $50\Omega$ r                           | termin<br>especti             | al voltage of 220 V. The armature and shunt vely. The iron and friction losses equals 900  |  |  |  |  |  |  |
| i)   | FMF generated   | ii)                           | Conner losses  |  |  |  |  |  |  |
| iii)   | Output of the prime mover   | iv)                           | Overall efficiency.  |  |  |  |  |  |  |
| )  |   | 1.)                           |  |  |  |  |  |  |  |
| Deri   | ive the torque equation of d. c. mot  | or. Hen                       | nce justify in series motor, $T_a \alpha I_a^2$ & in   |  |  |  |  |  |  |
| shur   | nt motor, $T_a \alpha I_a$ .  |                               |  |  |  |  |  |  |  |
| A 4-<br>rpm<br>has   | pole, 240 volt, wave connected shu<br>and drawing armature current and<br>540 conductors, its resistance is 0.2 | ınt mot<br>field cι<br>1Ω. As | tor gives 11.19 kW when running at 1000<br>urrent of 50 Amp and 1 Amp respectively. It<br>ssuming a drop of 1 volt per brush. Find:- |  |  |  |  |  |  |
| i)   | Total torque  | ii)                           | Useful torque  |  |  |  |  |  |  |
| iii)   | Flux per pole,  | iv)                           | Rotational losses and  |  |  |  |  |  |  |
| v)   | Efficiency.   |                               |  |  |  |  |  |  |  |
| Wh   |   |                               |  |  |  |  |  |  |  |
| w nat is the significance of back emf in d. c. motor.                                      |   |                               |  |  |  |  |  |  |  |
|  |   | O                             | R  |  |  |  |  |  |  |
| Exp  | lain the various methods of speed c   | control                       | of d. c. shunt motor.  |  |  |  |  |  |  |
| Ad.  | c. shunt motor with an armature res   | sistance                      | e of $0.4\Omega$ and field resistance of $100\Omega$ drives  |  |  |  |  |  |  |
| a load at 500 rpm taking 27 Amp from the line. It is desired to drive the same load at 750 |   |                               |  |  |  |  |  |  |  |
| rpm  | rpm. The load torque is constant. Calculate the value of resistance to be used as field                         |                               |  |  |  |  |  |  |  |
| regulator. Assume that the field core is not saturated.                                    |   |                               |  |  |  |  |  |  |  |
| A 3-   | -phase 4-pole, 50 Hz induction mot  | or has                        | a full load speed of 1440 rpm. For this motor  |  |  |  |  |  |  |
| calculate the following-   |   |                               |  |  |  |  |  |  |  |
| i)   | i) Full load slip and rotor current frequency.  |                               |  |  |  |  |  |  |  |
| ii)  | Speed of the stator field w.r.t.  |                               |  |  |  |  |  |  |  |
|  | a) Stator and   | b)                            | Rotor.   |  |  |  |  |  |  |
| iii)   | Speed of the rotor field w.r.t.   |                               |  |  |  |  |  |  |  |
|  | a) Rotor b) Sta   | tor and                       | l c) Stator field.   |  |  |  |  |  |  |
| Wri  | te short notes on   |                               |  |  |  |  |  |  |  |
| i)   | ) Shaded pole induction motor.  |                               |  |  |  |  |  |  |  |
| /  | т · · · · · · · · · · · · · · · · · · ·   |                               |  |  |  |  |  |  |  |

8

8

3

8

8

8

4

4

8

5

8

A 6-pole, 3-phase induction motor runs at a speed of 960 rpm when shaft torque is 136
 N.m and frequency 50 Hz. Calculate the rotor copper losses if friction and windage losses are 150 watt.

8

8

- **9.** a) Explain hunting in synchronous motor. What is the purpose of damper windings in synchronous machine?
  - b) Why the synchronous motor is not self starting? How it is made self started? Explain both the issues in detail.

## OR

- 10. a) What do you mean by regulation? Why the terminal voltage decreases when the load is connected to it?
  - b) An alternator requires an excitation of 2 Amp to produce a full load short circuit current of 8 60 Amp. The same excitation on open circuit gives an emf of 260 V. If resistance of armature is  $0.8\Omega$ ; find full load regulation:
    - i) On resistive load.
    - ii) On 0.8 leading p.f. load.
  - c) When 3-phase alternator is connected to unity power factor load, explain how the armature flux has cross magnetizing effect. 5

\*\*\*\*\*